

Concrete Edger Polishing Steps

Grinding / Honing

Step #1 30 grit metal (Start with 30 grit for large aggregate exposure finish)

Step #2 70 grit metal (Start with 70 grit for medium aggregate exposure finish)

Step# 3 120 grit metal (Start with 120 grit for a salt and pepper finish)

Step #4 100 grit Calibra's (Ceramic)

Step #5 Add Color if desired. (Recommend Ameripolish Surelock Dye)

Step #6 220 grit Vharr's

Step #7 Densify

Polishing

Step #8 400 grit Vharr's

Step #9 800 grit Vharr's

Step #10 1800 grit Vharr's

Step #11 Apply sealer/guard

Step #12 Burnish